-0009



State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



1594 West North Temple, Suite 1210

Kathleen Clarke Executive Director

Governor

Lowell P. Braxton Division Director

Michael O. Leavitt

PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340

801-359-3940 (Fax) 801-538-7223 (TDD) Partial: XXX Complete: Exploration: Inspection Date & Time: 4/19/2000 / 8:30a.m.-4:00p.m.

Date of Last Inspection: 3/15/2000

Mine Name: Cottonwood/Wilberg Mine County: Emery Permit Number: ACT/015/019
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 310, Huntington, Utah 84528
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Chuck Semborski and Dennis Oakley
State Officials(s): Bill Malencik Federal Official(s): None
Weather Conditions: Partly Cloudy, low 60's
Existing Acreage: Permitted- <u>11508</u> Disturbed- <u>102</u> RegradedSeededBonded- <u>102</u>
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded
Status: _Exploration/_XXX_Active/_Inactive/_Temporary Cessation/_Bond Forfeiture
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)
REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS
Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.

b. For <u>partial inspections</u> check only the elements evaluated.

- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		-	EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE		[XX]	Ц	[XX]	Ц
2.	SIGNS AND MARKERS		[XX]	Ц	Ļ	Ļ
3.	TOPSOIL		[XX]	Ш		Ш
4.	HYDROLOGIC BALANCE:					
a.	DIVERSIONS		[XX]	Ц		Ļļ
b.	SEDIMENT PONDS AND IMPOUNDMENTS		[XX]	Ц	XX	Ļ
c.	OTHER SEDIMENT CONTROL MEASURES		[XX]	Ц	XX	Ļļ
d.	WATER MONITORING		Ц	Ц	\coprod	ĻΫ
e.	EFFLUENT LIMITATIONS			Ц	Ц	Ļļ
5.	EXPLOSIVES		[XX]	Щ	\coprod	H
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		[XX]	ĻĻ		Ӊ
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		[XX]	H	[XX] [XX]	Ļļ
8.	NONCOAL WASTE		[XX]	Ш	[XX]	Ш
9.	PROTECTION OF FISH, WILDLIFE AND		F 3		f 3	f 1
10	RELATED ENVIRONMENTAL VALUES			Ц	<u> </u>	Щ
10.	SLIDES AND OTHER DAMAGE		[XX]	Ц	\coprod	닏
11.	CONTEMPORANEOUS RECLAMATION		Ļ	Щ	ĻĻ	닏
12.	BACKFILLING AND GRADING		Ц	ĻĻ	\coprod	닏
13.	REVEGETATION		Ļļ	ĻĻ		Ļ
14.	SUBSIDENCE CONTROL		. 📙	H		Ц
15.	CESSATION OF OPERATIONS		Ш	ш		ш
16.	ROADS:		(3/3/3	r n	r i	r 1
a.	CONSTRUCTION/MAINTENANCE/SURFACING		[XX]	Ļļ		
b.	DRAINAGE CONTROLS		<u></u>	لِـلِ		
17.	OTHER TRANSPORTATION FACILITIES		Ļ	ų.	H	닏
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS		<u> </u>	H		<u> </u>
19.	AVS CHECK (4th Quarter-April, May, June) (date)		<u> </u>	Щ		<u> </u>
20.	AIR QUALITY PERMIT			Ļ	[XX]	닌
21	RONDING & INSURANCE		[XX]	1 1	IXXI	1 1

INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>3</u>

PERMIT NUMBER: ACT/015/019

DATE OF INSPECTION: 4/19/2000

(Comments are Numbered to Correspond with Topics Listed Above)

SUMMARY

-No violations were issued as a result of the instant inspection.

- -The ninth east portals are reclaimed. The operator has done a good job of reclaiming this area.
- -A hearing before the board will be held on 2/23/2000 on the issue of the disturbed area. PacifiCorp's position is the reclamation agreement and the disturbed boundary applies only to the disturbed area. The Division's position is that it applies to the entire permit area. The board's decision was in favor of the permittee.

1. PERMIT

A Division Order was issued to PacifiCorp Mines to update the permit and the disturbed areas.

The revised permit has been approved by DOGM and expires July 6, 2004.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

There are five sediment ponds. Two at the Cottonwood/Wilberg mine, MSHA ponds, and commonly referred to as the north and south impoundments.

There are two small sediment ponds at the Cottonwood Fan Portal. These are incised sediment ponds. The permittee is working with Sharon Falvey on reclaiming the two sediment ponds.

All impoundments are designed and details included in the MRP on the north and south impoundments. MSHA made a determination as follows:

- (1) The capacity of both ponds are such that MSHA approval was granted.
- (2) Both ponds would be inspected monthly and a variance was granted.
- (3) Both ponds would not require an open channel spillway per OSM granted variance.

All ponds were inspected as required.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The mine utilizes sumps, silt fences, and straw bales to treat disturbed runoff. Most of the aforementioned devices are redundant control measures.

The mine has nine approved alternative sediment control sites where the runoff is controlled by alternative sediment control measures. These areas include Miller Canyon, sewer absorption field, Cottonwood Fan Portal, waste rock site outslope, guard station, conveyor pad, tube conveyor access road, Wilberg fan, and 9th east breakout. The 9th east breakout was reclaimed in the fall of 1999.

INSPECTION REPORT

(Continuation sheet)

Page <u>3</u> of <u>3</u>

PERMIT NUMBER: ACT/015/019

DATE OF INSPECTION: 4/19/2000

(Comments are Numbered to Correspond with Topics Listed Above)

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

Coal mine waste is stored west of State Highway 57 on federal land. The permittee has a ROW grant from BLM. Waste rock site services the Cottonwood/Wilberg, Trail Mountain, and Des Bee Dove mines. See comment on page 2 on a deletion of 12.98 acres of undisturbed DOGM permitted area. USFS has submitted favorable comments. The 12.98 acres has been approved by the Division. A 10' buffer zone has been established between the PacifiCorp Class I road and the Texaco drill site.

8. NONCOAL WASTE

Noncoal waste is stored on the surface of the mine site in a designated area. Thereafter, the waste is transported to and stored at an approved landfill.

21. BONDING AND INSURANCE

On February 24, 2000, Pam sent the PFO a copy of the new Liability Insurance for Cottonwood Mine.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Chuck Semborski (PacifiCorp) Henry Austin (OSM)
Given to: Pam Grubaugh-Littig (DOGM) Filed to: Price Field Office

Date: April 25, 2000

Inspector's Signature: #26

Wm. J. Malencik